CO

OUT-65988 248er.68 W 111

DISTRIBUTION.

OFFICE FILE25X1

CABLE SEC.

PP&B/RD

SECUR.

PSG/00

RRD REPRO

AID IEG

PROD

MEST

EAST

Ma:S

POM

DYA-AP

25X1

DIA-25X1

SCIEN

TSSG

R 232352Z SEP 63 FM NPIC WASHDC TO AIG 7840

BI

C O N F I D E N T I A L CITE NPIC 4635.

CPIR:NPIC SER:FØØ881UEYT MSN:ØØ977P 29AUG68H

DAY PHOTO. CAMERA ON/OFF TIMES UNK. AMS SERIES L7Ø15, SHEETS 6438 II, III, 1ST ED.

PART I. SIGNIFICANT PHOTO INTERPRETATIONS

B. NEW TARGETS AND SIGNIFICANT CHANGES

ZZZØ1:ROUTE 11Ø SERVICEABILITY SGM:11ØB CTY:LA 144231N1Ø7Ø6 ZE Z A 12-NM SEGMENT OF ROUTE 11Ø, TOGETHER WITH ITS ADJACENT ALTERNATE AND BY-PASS ROAD NETWORK, IS OBSERVED FROM 14-42-31N 107-06-402 (UTM YB27227Ø) EAST TO ITS JUNCTION WITH ROUTE 96 AT 14-42-41N 107-18-17E (YB480275). THIS SEGMENT IS IN DISUSE AND THE ROAD CONDITION IS POOR. MONSOON RAINS HAVE CAUSED MAJOR DAMAGE TO THE ROADBED, WASHING IT COMPLETELY AWAY AT YB417296, YB347268, AND YB327264.

ZZZ 02:ROUTE 96 SERVICEABILITY SGM:96E CTY:LA 144520N107165 E A 3.5-NM SEGMENT OF ROUTE 96 IS OBSERVED FROM THE ROUTE 96/110 JUNCTION AT 14-45-20N 107-16-55E (UTM YB456323) SOUTHEAST TO 14-42-15N 107-16-55E (YB484267). THE ROAD IS OVERGROWN IN NUMEROUS PLACES AND APPEARS TO BE IN DISUSE. THE THREE CROSSINGS OVER THE DAK XOU RIVER (AT YB457323, YB455316, YB458311) ALSO APPEAR TO BE IN DISUSE.

ADVANCE CY SANITIZED WITH TEXT 25X1

PART II. OTHER PHOTO INTERPRETATIONS - NONE GP-1 C O N F I D E N T I A L

-- END OF MESSAGE --

CONFIDENTIAL